



**Site:** Detroit Windshield Survey (1539 E Grand Blvd)

**Photograph No.:** 1

**Date:** 5/13/2010

**Direction:** Northwest

**Photographer:** David Sena

**Subject:** East building frontage (North Series) along E Grand Blvd and Concord Street.



**Site:** Detroit Windshield Survey (1539 E Grand Blvd)


**Photograph No.:** 2

**Date:** 5/13/2010

**Direction:** Southwest

**Photographer:** David Sena

**Subject:** East building frontage (Middle Series) at the corner of E Grand Blvd and Concord Street.



**Site:** Detroit Windshield Survey (1539 E Grand Blvd)

**Photograph No.:** 3

**Date:** 5/13/2010

**Direction:** South

**Photographer:** David Sena

**Subject:** East building frontage (Middle Series and South Series) along Concord Street.



**Site:** Detroit Windshield Survey (1539 E Grand Blvd)

**Photograph No.:** 4

**Date:** 5/13/2010

**Direction:** Down

**Photographer:** David Sena

**Subject:** Pile of trash and deteriorated building materials in a Middle Series building.



**Site:** Detroit Windshield Survey (1539 E Grand Blvd)


**Photograph No.:** 5

**Direction:** South

**Subject:** Trash and bulk debris in a Middle Series Building

**Date:** 5/13/2010

**Photographer:** David Sena



**Site:** Detroit Windshield Survey (1539 E Grand Blvd)

**Photograph No.:** 6

**Direction:** Southeast

**Subject:** Boat and other trash and bulk debris in a Middle Series building.

**Date:** 5/13/2010

**Photographer:** David Sena



**Site:** Detroit Windshield Survey (1539 E Grand Blvd)


**Photograph No.:** 7

**Direction:** Northwest

**Subject:** Trash and bulk debris in a North Series building.

**Date:** 5/13/2010

**Photographer:** David Sena



**Site:** Detroit Windshield Survey (1539 E Grand Blvd)


**Photograph No.:** 8

**Direction:** Northwest

**Subject:** West building frontage (North Series) along an unnamed alley.

**Date:** 5/13/2010

**Photographer:** David Sena



**Site:** Detroit Windshield Survey (1539 E Grand Blvd)

**Photograph No.:** 9

**Date:** 5/13/2010

**Direction:** Northwest

**Photographer:** David Sena

**Subject:** Piles of dirt and crushed building materials west of the North Series buildings.



**Site:** Detroit Windshield Survey (1539 E Grand Blvd)

**Photograph No.:** 10

**Date:** 5/13/2010

**Direction:** North

**Photographer:** David Sena

**Subject:** Piles of dirt and crushed building materials west of an exposed basement and the North Series buildings.





**Site:** Detroit Windshield Survey (1539 E Grand Blvd)

**Photograph No.:** 11

**Date:** 5/13/2010

**Direction:** Northeast

**Photographer:** David Sena

**Subject:** Utility tunnel entrance from the exposed basement west of the North Series buildings.



**Site:** Detroit Windshield Survey (1539 E Grand Blvd)

**Photograph No.:** 12

**Date:** 5/13/2010

**Direction:** Northeast

**Photographer:** David Sena

**Subject:** Spilled material from a 55-gallon fiber drum west of the North Series buildings.



**Site:** Detroit Windshield Survey (1539 E Grand Blvd)


**Photograph No.:** 13

**Date:** 5/13/2010

**Direction:** Northeast

**Photographer:** David Sena

**Subject:** Pile of ash near an old furnace along the west side of a North Series building.



**Site:** Detroit Windshield Survey (1539 E Grand Blvd)

**Photograph No.:** 14

**Date:** 5/13/2010

**Direction:** Down

**Photographer:** David Sena

**Subject:** Drum and pile of unknown material in a utility tunnel west of the North Series buildings.



**Site:** Detroit Windshield Survey (1539 E Grand Blvd)

**Photograph No.:** 15

**Date:** 5/13/2010

**Direction:** East

**Photographer:** David Sena

**Subject:** Drum with unknown liquid contents along the west side of a North Series building.



**Site:** Detroit Windshield Survey (1539 E Grand Blvd)

**Photograph No.:** 7

**Date:** 5/13/2010

**Direction:** West

**Photographer:** David Sena

**Subject:** Partially buried drums in the northwest corner of the property.